

## Water quality testing at four river water intakes of NWSC in Pokhara University

*Status: Completed*

**Project Partner:** CREEW  
**Project Area:** Pokhara, Nepal  
**Project Duration:** August 2015- September 2015

**Aim:**

To determine the water quality status of different water sources and points such as river water intakes, water reservoir and households' tap water.

**Project Description:**

Quality of drinking water is growing issue in Nepal. ENPHO had collaborated with CREEW to perform the water quality survey in Pokhara, which is a part of "Preparatory Survey on Pokhara Water Supply Improvement Project" being supported by JICA Grant Aid Project.



**Project Outputs:**

- Performed water quality sampling and analysis of 4 river water intakes, 2 water reservoirs and 100 tap water from households;
- Prepared consolidated report on the water quality status of different source in Pokhara.

**Project Achievements:**

- Determined state of water quality for dry and wet seasons for drinking water supply systems supported by Pokhara Water Supply Improvement Project.

**Beneficiaries:**

- Residence of Pokhara valley